



Bürkle Standard-Programm

parameter name	recommended value
adhesive	PU dispersion (1 or 2 components)
temperature heating plate	120°C
preheating time	90 sec
prevacuum time	0 sec
vacuum time	6 sec
pressing pressure	4,5 bar
pressing time	30 sec

***Please note that these are merely recommended press settings and results may vary depending on your individual press, setup, or any other variables.**